

4-13-2015

Bracket Modification

Features:

The previous bracket worked well until another design change resulted in the project box hitting the bottom of the bracket. The second slot was not needed (was there for redundancy), and was deleted, with the resulting bracket below:

